City of Boise ADA Assessment

Appendix A – Boise Airport

05/21/2021

Report # TO21-B027 (Part 1)











Facility:

4322

Boise Airport

Location: 1st Floor Accessible Parking

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

There is no signage present identifying the accessible parking spaces.

RECOMMENDATIONS

Install an accessible parking sign at each accessible space at a minimum height of 60" above the ground.











Facility:

4157 Boise Airport

Location: 1st Floor Accessible Parking

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3

The access aisles are not of sufficient width due to concrete poles.

RECOMMENDATIONS

Move the parking bumpers forward so that the entire usable width of the parking space is 96" and the entire usable width of the access aisle is 60".

The accessible route must be maintained even when cars are parked and overhang the bumpers.











Facility:

4153

Boise Airport

Location: 1st Floor Accessible Parking

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3


The accessible route passes behind parked vehicles.

RECOMMENDATIONS


For the purposes of achieving greater accessibility and Human Centric Design, move the parking bumpers forward to allow for the 36" wide accessible route to go in front of the vehicles rather than behind.

The accessible route must be maintained even when cars are parked and overhang the bumpers. This will require adjusting all the bumpers on this row to allow for a continuous route.











Facility:

3800

Boise Airport

Location: 18t

Location: 1st Floor Accessible Parking D10

Schedule: 2021

Estimated Cost: \$5,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §502.5

There are beams in the accessible parking space.

The closest space to the accessible route is not accessible.

RECOMMENDATIONS

Relocate the existing accessible parking space to be the space closest to the accessible route or move the parking bumpers forward so that the entire usable width of the parking space is 96" and the entire usable width of the access aisle is 60".











Facility:

3994

Boise Airport

Location: 1st Floor Accessible Parking Ramp

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 5" into the circulation space at 30" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.









Facility:

4180

Boise Airport

Location: Totalo

Location: 1st Floor Accessible Parking Ramp

Schedule: 2023

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502, §502.3


The accessible route goes behind parked vehicles and is not marked.


The painted lines for the accessible parking spaces are faded.

RECOMMENDATIONS

For the purposes of achieving greater accessibility and Human Centric Design, mark the access aisle in front of the parked vehicles to enhance pedestrian safety.

It is safer to have the accessible route not go behind vehicles. Restripe and repaint the accessible parking spaces, access aisles, and ISA symbols.







Facility:

3504

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

There is no signage present identifying two of the accessible parking spaces.

RECOMMENDATIONS

Install an accessible parking sign at each accessible space at a minimum height of 60" above the ground.







Facility:

3696

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4


The tactile sign identifying the room is not in the correct location at 60.75" above the floor.

RECOMMENDATIONS

Reinstall the sign on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.









Facility:

3315

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2021

Estimated Cost: \$400.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6


The accessible parking signs are 52" above the ground.

RECOMMENDATIONS

Remount the accessible parking signs at each accessible space at a minimum height of 60" above the ground.











Facility:

3196

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2023

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §206.8

A bollard and garbage can encroaches on the access aisle reducing its width.

RECOMMENDATIONS

Relocate the bollard and garbage can from the access aisle to ensure that the width of the access aisle is 60" for the entire length of the accessible parking space.









Facility:

3026

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2021

Estimated Cost: \$1,000.00

Priority Score 2 MEDIUM LOW Quick Fix: No Built before ADA: No

VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §208.2.4

There are no marked "Van accessible" spaces.

RECOMMENDATIONS

Add a 132" wide van accessible parking space for every six vehicle parking spaces. Add a "van accessible" parking sign at a minimum height of 60" above the ground.







Facility:

3598

Boise Airport

Location: 1st Floor New Parking Garage 1A5

Schedule: 2023

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA 2010 ADA Standards for Accessible Design Codes: §502

The painted lines for the accessible parking spaces are missing on one side of two spaces.

RECOMMENDATIONS

Paint the missing lines at the two accessible parking spaces.







Facility:

3949

Boise Airport

Location: 2nd Floor Women's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2, §308.2.1


The dispenser is outside of the unobstructed forward reach range at 48.25" above the floor.

The dispenser protrudes 6.5" into the circulation space at 48.25" above the floor.

RECOMMENDATIONS

Lower the dispenser by 0.25" to meet the accessible reach range of 48" maximum above the floor.

Recess the dispenser so it protrudes a maximum of 4" or place a cane detectable object beneath it.









Facility:

4167

Boise Airport

Location: 2nd Floor Parking Garage Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The paper towel dispenser protrudes 8" into the circulation space at 45" above the floor.

RECOMMENDATIONS

Recess the paper towel dispenser so it protrudes a maximum of 4" or place a cane detectable object beneath it.









Facility:

4280

Boise Airport

Location: 2nd Floor Parking Garage

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 6.75" into the circulation space at 29.75" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.









Facility:

3834

Boise Airport

Location: 2nd Floor Parking Garage Restroom

Schedule: 2021

Estimated Cost: \$200.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4

The tactile sign identifying the room is not in the correct location.

RECOMMENDATIONS

Reinstall the sign on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.











Facility:

3886

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §604.7

The toilet paper dispenser is located out of the accessible reach range.

RECOMMENDATIONS

Remount the toilet paper dispenser to 7" minimum and 9" maximum in front of the water closet measured to the centerline of the dispenser.

The outlet of the dispenser shall be 15" minimum and 48" maximum above the floor and shall not be located behind the water closet.











Facility:

4085

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §308.2.1

The hook is outside of the unobstructed forward reach range at 66" above the floor.

RECOMMENDATIONS

Lower the hook by 18" to meet the accessible reach range of 48" maximum above the floor.









Facility:

4086

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.8.1.2

The door to the accessible water closet is not self closing.

Either self-closing hinges are not installed on the door or if installed, they are defective.

RECOMMENDATIONS

Install or reinstall self-closing hinges on the door to ensure that the door is self-closing per the ADA requirements.







Facility:

3883

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2021

Estimated Cost: \$500.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.5.1

The side grab bar is located 3.75" from the rear wall.

RECOMMENDATIONS

Remount the side grab bar 12" maximum from the rear wall and extending 54" minimum from the rear wall.











Facility:

3885

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: ICC A117.1 §604.5.1

There is no vertical grab bar

RECOMMENDATIONS

Install an 18" long (minimum) vertical grab bar on the side wall. The grab bar shall be mounted with the bottom located at 39" minimum and 41" maximum above the floor.

The centerline of the vertical grab bar shall be located 39" minimum and 41" maximum from the rear wall.











Facility:

4506

Boise Airport

Location: 2nd Floor Accessible Parking Women's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §604.2

The centerline of the toilet is located 19" from the sidewall.

RECOMMENDATIONS

Reposition the centerline of the toilet to be within 16" minimum and 18" maximum from the sidewall. Install vertical grab bars with a minimum length of 18".













Facility:

4246

Boise Airport

Location: 2nd Floor Departure Garage

Schedule: 2023

Estimated Cost: \$0.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §707

The interactive touch screen does not have any sound or tactile components.

Therefore, a visually impaired person would not be able to access the information provided by the kiosk.

RECOMMENDATIONS

Audio instructions must be provided to guide the user through all the functions of the machine. This is to accommodate an individual sitting in the back seat who requires non-visual access to the equipment.

Tactile instructions must be provided informing the user on the method of activating the audio instructions.







Facility:

3854

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4

The tactile sign identifying the room is not in the correct location.

RECOMMENDATIONS

Reinstall the sign on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.







Facility:

3889

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The paper towel dispenser protrudes 8" into the circulation space at 46" above the floor.

RECOMMENDATIONS

Recess the paper towel dispenser so it protrudes a maximum of 4" or place a cane detectable object beneath it.









Facility:

3904

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §604.7

The toilet paper dispenser is located out of the accessible reach range.

RECOMMENDATIONS

Remount the toilet paper dispenser to 7" minimum and 9" maximum in front of the water closet measured to the centerline of the dispenser.

The outlet of the dispenser shall be 15" minimum and 48" maximum above the floor and shall not be located behind the water closet.







Facility:

3948

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2, §308.2.1


The sharps dispenser is outside of the unobstructed forward reach range at 49" above the floor.

The sharps dispenser protrudes 5" into the circulation space at 49" above the floor.

RECOMMENDATIONS

Lower the sharps dispenser by 1" to meet the accessible reach range of 48" maximum above the floor.

Recess the sharps dispenser so it protrudes a maximum of 4" or place a cane detectable object beneath it.







Facility:

4012

Boise Airport

2004110111 2114 1 100

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §606.5

The pipes under the sink are not covered.

RECOMMENDATIONS

Wrap the pipes beneath the sink with soft protective wrap or plastic.







Facility:

4102 Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.8.1.2

The door to the accessible water closet is not self closing. Either self-closing hinges are not installed on the door or if installed, they are defective.

RECOMMENDATIONS

Install or reinstall self-closing hinges on the door to ensure that the door is self-closing per the ADA requirements.





Facility:

4144

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §308.2.1

The coat hook is outside of the unobstructed forward reach range at 63" above the floor.

RECOMMENDATIONS

Lower the coat hook by 15" to meet the accessible reach range of 48" maximum above the floor.







Facility:

4078

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §604.2

The centerline of the toilet is located 19.5" from the sidewall.


RECOMMENDATIONS

Reposition the centerline of the toilet to be within 16" minimum and 18" maximum from the sidewall.











Facility:

4079

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.6

The flush control is located on the wall side of the toilet.

RECOMMENDATIONS

Either make the toilet flush automatically or relocate the flush control to be operated on the open side of the toilet.







Facility:

4133

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: ICC A117.1 §604.5.1

The accessible water closet does not have a vertical grab bar.

RECOMMENDATIONS

Install an 18" long (minimum) vertical grab bar on the side wall. The grab bar shall be mounted with the bottom located at 39" minimum and 41" maximum above the floor.

The centerline of the vertical grab bar shall be located 39" minimum and 41" maximum from the real wall.









Facility:

4134

Boise Airport

Location: 2nd Floor Departure Garage Men's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.5.2

The rear grab bar is centered on the toilet.

RECOMMENDATIONS

Replace the rear grab bar with one that is a minimum of 36" long minimum and extends from the centerline of the water closet 12" minimum on one side and 24" minimum on the other.









Facility:

4352

Boise Airport

Location: 2nd Floor New Parking Garage

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4

The tactile sign identifying the room is too high.

RECOMMENDATIONS

Reinstall the sign on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.







Facility:

4443

Boise Airport

Location: 2nd Floor New Parking Garage

Schedule: 2021

Estimated Cost: \$500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

One accessible parking space sign is missing. The four existing accessible parking space signs are 52" above the ground.


RECOMMENDATIONS

Install/readjust the height of an accessible parking sign at each accessible space at a minimum height of 60" above the ground.











Facility:

4445 Boise Airport

Location: 2nd Floor New Parking Garage

Schedule: 2021

Estimated Cost: \$500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502

The painted lines for the accessible parking spaces are missing along the crosswalk.

RECOMMENDATIONS

Paint the boundary line for accessible parking space along the crosswalk.





Facility:

4446

Boise Airport

Location: 2nd Floor New Parking Garage

Schedule: 2023

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §206.8

A bollard encroaches on the yellow painted access aisle reducing its width.

RECOMMENDATIONS

Add a parking bumper to ensure that the column and bollard are not encroaching on the adjacent access aisle.








Facility:

4444 Boise Airport

Location: 2nd Floor New Parking Garage

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §208.2.4

There are no marked "Van accessible" spaces.

RECOMMENDATIONS

Add a 132" wide van accessible parking space for every six vehicle parking spaces. Add a "van accessible" parking sign at a minimum height of 60" above the ground.











Facility:

3087

Boise Airport

Location: 2nd Floor Parking Garage D10

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 6.5" into the circulation space at 31" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.







Facility:

3169

Boise Airport

Location: 2nd Floor Parking Garage D10

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3

The garbage can is obstructing the access route.

RECOMMENDATIONS

Relocate the garbage can so it is not located within the access aisle or blocking the ramp's handrails and accessible route.







Facility:

3687 Boise Airport

Location: 2nd Floor Parking Garage D10

Schedule: 2021

Estimated Cost: \$500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.5

There is a metal pole in the accessible route and interfering with the accessible parking space.

RECOMMENDATIONS

Remove the metal pole from access aisle.







Facility:


3156

Boise Airport

Location: 2nd Floor Parking Garage D10

Schedule: 2021

Estimated Cost: \$5,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 3% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.











Facility:

3773

Boise Airport

Location: 2nd Floor Parking Garage Ramp

Schedule: 2021

Estimated Cost: \$5,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2

The running slope of the ramp is between 8.7% and 8.9%.

RECOMMENDATIONS

Resurface the ramp to reduce the running slope to a maximum of 8.3%.











Facility:

4027

Boise Airport

Location: Line i

Location: 2nd Floor Parking Garage to Departure

Schedule: 2021

Estimated Cost: \$2,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §406.3

The curb ramp flares have a 11.6% slope.

RECOMMENDATIONS

Resurface the curb ramp flares to ensure a maximum slope of 10%.











Facility:

4026

Boise Airport

Location: 2nd Floor Parking Garage to Departure

Schedule: 2021

Estimated Cost: \$3,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2, §705

The curb ramp does not have a detectable warning.

The running slope of the curb ramp is 9.3%.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".

Reconstruct the curb ramp to reduce the running slope to a maximum of 8.3%.









Facility:

3008

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §705

The curb ramps do not have detectable warnings.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".







Facility:

3107

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §705

The curb ramps do not have detectable warnings. This is located in the Departures Terminal for United.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".











Facility:

3109

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §406.2

There is an abrupt change in vertical elevation where the curb ramp meets the sidewalk.

This is located in the Departures Terminal for Allegiant, Delta, and American.

RECOMMENDATIONS

Regrade the transition to ensure that the vertical change in elevation does not exceed 0.25".













Facility:

3132

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §303.2

There is a change in level greater than 0.25".

RECOMMENDATIONS

Resurface the pathway to reduce the change in level to less than 0.25" or 0.5" if beveled.









Facility:

3691

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §303.2

There is a 1.5" step at the base of the curb ramp.

This is located in the Departures Terminal for Southwest.


RECOMMENDATIONS

Resurface the pathway to reduce the change in level to less than 0.25" or 0.5" if beveled.











Facility:

3110 Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §302.1

There is a change in level at the top of the curb ramp due to a large crack. This is located in the Departures Terminal for Allegiant, Delta, and American.

RECOMMENDATIONS

Repave the top of the curb ramp to remove the crack.











Facility:

3111

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §406.3

The curb ramp flares have slopes of 10.7% and 11.3%.

This is located in the Departures Terminal for Allegiant, Delta, and American.

RECOMMENDATIONS

Resurface the curb ramp flares to ensure a maximum slope of 10%.













Facility:

3108

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2022

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2

The running slope of the curb ramp is 9.8%.

This is located in the Departures Terminal for Allegiant, Delta, and American.

RECOMMENDATIONS

Reconstruct the curb ramp to reduce the running slope to a maximum of 8.3%.











Facility:


3131

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal

Schedule: 2021

Estimated Cost: \$5,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §403.3

The route has a running slope of 10%.

RECOMMENDATIONS

Resurface the route to reduce the running slope to a maximum of 5%.







Facility:

3096

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Alaska Airlines)

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §308.2.1

The newspaper stand is outside of the unobstructed forward reach range at 53" above the floor.

RECOMMENDATIONS

Lower the newspaper stand by 5" to meet the accessible reach range of 48" maximum above the floor.









Facility:

3485

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Alaska Airlines)

Schedule: 2022

Estimated Cost: \$500.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §705

The curb ramps do not have detectable warnings.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".









Facility:

3486

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Alaska Airlines)

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §303.2


There is an abrupt change in vertical elevation where the curb ramp meets the sidewalk resulting in a change in level greater than 0.25".

RECOMMENDATIONS

Resurface the pathway to reduce the change in level to less than 0.25" or 0.5" if beveled.











Facility:

3484

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Alaska Airlines)

Schedule: 2021

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §406.3


The curb ramp flares have a 10.6% to 11.4% slope.

RECOMMENDATIONS

Resurface the curb ramp flares to ensure a maximum slope of 10%.











Facility:

3482

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Alaska Airlines)

Schedule: 2022

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2

The running slope of the curb ramp is 10.5%.

RECOMMENDATIONS

Reconstruct the curb ramp to reduce the running slope to a maximum of 8.3%.









Facility:

3690

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Southwest)

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §705


The curb ramps do not have detectable warnings.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".









Facility:

3692

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Southwest)

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2


The running slope of the curb ramp is 9.3%.

RECOMMENDATIONS

Resurface the curb ramp to reduce the running slope to a maximum of 8.3%.









Facility:

3693

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Southwest)

Schedule: 2021

Estimated Cost: \$2,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §406.3

The curb ramp flares have a 10.8% and 13.2% slope.


RECOMMENDATIONS

Resurface the curb ramp flares to ensure a maximum slope of 10%.











Facility:

3694

Boise Airport

Location: 2nd Floor Parking Garage to Departures Terminal (Southwest)

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.5


The curb ramp is 34" wide.

RECOMMENDATIONS

Expand the curb ramp to be a minimum width of 36".









Facility:

4324

Boise Airport

Location: 3rd Floor Accessible Parking

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 2.3% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.











Facility:

3359

Boise Airport

Location: 3rd Floor New Parking Garage 3A5

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4

The tactile sign identifying the room is not in the correct location at 60.5" above the floor.

RECOMMENDATIONS

Reinstall the sign on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.







Facility:

3392

Boise Airport

Location: 3rd Floor New Parking Garage 3A5

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking sign is 51" above the ground.

RECOMMENDATIONS

Remount the accessible parking sign at a minimum height of 60" above the ground.











Facility:

3668

Boise Airport

Location: 3rd Floor New Parking Garage 3A5

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 6" into the circulation space at 29.5" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it or relocate so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.







Facility:

3391

Boise Airport

Location: 3rd Floor New Parking Garage 3A5

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §502

There are no markings on the side of the space closest to the yellow crosswalk.

RECOMMENDATIONS

Paint the accessible parking space to completion by adding a line along the yellow crosswalk.












3706 Boise Airport

Facility:

Location: 3rd Floor New Parking Garage 3A5

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 2.9% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.





Facility:

3338

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 7" into the circulation space at 30.5" above the floor.


RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.

Or relocate it outside of the accessible route.









Facility:

3433

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The van accessible parking sign is 60.5" above the ground.

RECOMMENDATIONS

Remount the accessible parking sign at a minimum height of 60" above the ground.





Facility:

3767

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 6.75" into the circulation space at 30" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.









Facility:

3067

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §505.2

The slope of the ramp is 6.5% and there are no handrails.

RECOMMENDATIONS

Install handrails at a minimum height of 34" and maximum of 38" above the ground. Make sure there are adequate handrail extensions both at the top and bottom of the handrail. OR reduce the running slope to a maximum of 5%.







Facility:

3119

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.5

The vertical clearance at the van accessible parking space is 95" above the ground. At the top of the space, the height is reduced to 90" above the ground.

RECOMMENDATIONS

Make sure the vertical clearance of the van accessible parking space and access aisle is 98" minimum. Accessible parking spaces shall be a minimum width of 144" with 60" wide access aisles.

This may require moving the spaces to another location that meets the minimum height requirement. Ensure that the entire route leading to the van accessible parking space is of sufficient height.







Facility:

3423

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §502.3

The accessible parking spaces and access aisles are not of sufficient width due to concrete poles.

RECOMMENDATIONS

Install parking bumpers to ensure that accessible parking spaces are a minimum of 96" wide, van parking spaces are a minimum of 132" wide, and their adjacent access aisles are a minimum of 60" wide.

The accessible route must be continuous even when cars are parked and overhang the bumpers.







Facility:

3601

Boise Airport

Location: 3rd Floor Parking Garage D11

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §502.2

The accessible parking space is 91" wide.

RECOMMENDATIONS

Install an accessible parking space that is a minimum of 96" wide with an adjacent aisle that is a minimum of 60" wide.

Ensure at least one accessible parking space is marked as "van" accessible.







Facility:

4033

Boise Airport

Location: 4th Floor New Parking Garage

Schedule: 2021

Estimated Cost: \$200.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §703.4

The tactile signs identifying the rooms are not in the correct location as they are too high above the ground.

RECOMMENDATIONS

Reinstall the signs on the latch side of the door at 48" minimum above the floor measured from the baseline of the lowest character and 60" maximum measured from the baseline of the highest character.









Facility:

3411

Boise Airport

Location: 4th Floor New Parking Garage 4A5

Schedule: 2021

Estimated Cost: \$400.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking signs are between 53" and 55" above the floor.

RECOMMENDATIONS

Remount the accessible parking signs at a minimum height of 60" above the ground.







Facility:

3200

Boise Airport

Location: 4th Floor New Parking Garage 4A5

Schedule: 2021

Estimated Cost: \$4,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3

The access aisles are not of sufficient width due to concrete poles.

RECOMMENDATIONS

Repaint the accessible parking spaces and access aisles so that all accessible car parking spaces are a minimum of 96" wide, van parking spaces are a minimum of 132" wide, and their adjacent access aisles are a minimum of 60" wide. This may require relocating the parking bumper.





Facility:

3013

Boise Airport

Location: 4th Floor Parking Garage

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §307.2

The fire extinguisher protrudes 6.75" into the circulation space at 29" above the floor.

RECOMMENDATIONS

Recess the fire extinguisher so it protrudes a maximum of 4", lower it so the bottom edge is 27" maximum above the floor, or place a cane detectable object beneath it.









Facility:

3581

Boise Airport

Location: 4th Floor Parking Garage

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.5

The vertical clearance at the van accessible parking space is 96".

RECOMMENDATIONS

Van accessible parking requires a minimum vertical clearance of 98". Relocate the van accessible parking to a location that meets this requirement.





Facility:

3340

Boise Airport

Location: 4th Floor Parking Garage

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §404.2.4.4, §703

The entrance has a 5.7% slope and no room signage.

RECOMMENDATIONS

Resurface the entryway to reduce the running slope to a maximum of 2% in all directions. Install tactile signage on the latch side of the doorway at a height of 48" minimum to 60" maximum above the floor. Signs shall be Braille with raised lettering and should be placed on the wall in the center of an 18"x18" clear floor space.









Facility:

3141

Boise Airport

Location: 4th Floor Parking Garage

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §403.3

The running slope is 6.5%.

RECOMMENDATIONS

Reconstruct the route to reduce the running slope to a maximum of 5%. Or install handrails at a minimum height of 34" and maximum of 38" above the ground. Make sure there are adequate handrail extensions both at the top and bottom of the handrail.







Facility:

3944

Boise Airport

Location: Contractor Lot Accessible Parking Elevator

Schedule: 2021

Estimated Cost: \$500.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §308.2.1

The button is outside of the unobstructed forward reach range at 56" above the floor.

RECOMMENDATIONS

Lower the button by 8" to meet the accessible reach range of 48" maximum above the floor.

Relocate the button to a location with a leveled clear floor space of 30"x48" with a maximum slope of 2%.







Facility:

3942

Boise Airport

Location: Contractor Lot Accessible Parking Elevator

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.7.2, §405.7.3

The landing is 48" deep and 64" wide.

RECOMMENDATIONS

Expand the provided landing to ensure that the clear length is 60" long minimum perpendicular to the door allowing adequate turning space.









Facility:

3941

Boise Airport

Location: Contractor Lot Accessible Parking Elevator

Schedule: 2022

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2

The running slope of the ramp is 20%.

RECOMMENDATIONS

Reconstruct the ramp to reduce the running slope to a maximum of 8.3%.





Facility:

3943

Boise Airport

Location: Contractor Lot Accessible Parking Elevator

Schedule: 2022

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2

The running slope of the ramp is 14.6%.

RECOMMENDATIONS

Reconstruct the ramp to reduce the running slope to a maximum of 8.3%.









Facility:

3932

Boise Airport

Location: Economy Lot Shuttle Stop C Parking

Schedule: 2021

Estimated Cost: \$200.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §406.4

Due to the garbage cans, the landing clear width is less than 36".

RECOMMENDATIONS

Relocate the garbage cans outside of the landing area.







Facility:

4358

Boise Airport

Location. Location

Location: Economy Lot Shuttle Stop C Parking

Schedule: 2021

Estimated Cost: \$200.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking signage is 54" above the ground.

RECOMMENDATIONS

Remount the accessible parking sign at each accessible space at a minimum height of 60" above the ground.









Facility:

4360

Boise Airport

Location: Economy Lot Shuttle Stop C Parking

Schedule: 2021

Estimated Cost: \$200.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking sign is 54" above the ground.

RECOMMENDATIONS

Remount the accessible parking sign at each accessible space at a minimum height of 60" above the ground.









Facility:


4357

Boise Airport

Location: Economy Lot Shuttle Stop C Parking

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The North West parking space has a 2.6% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.









Facility:

3897 Boise Airport

Location: Economy Parking Lot for Concessions and Airlines

Schedule: 2021

Estimated Cost: \$300.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking signs are 53.5" to 54.5" above the ground.

RECOMMENDATIONS

Install an accessible parking sign at each accessible space at a minimum height of 60" above the ground.











Facility:

3896

Boise Airport

Location: Economy Parking Lot for Concessions and Airlines

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space closest to the entrance has a 3.5% running slope and 2.5% cross slope.

RECOMMENDATIONS

Reconstruct the parking space to reduce the slope to a maximum of 2% in all directions.











Facility:

3895

Boise Airport

Location: Economy Parking Lot for Concessions and Airlines

Schedule: 2021

Estimated Cost: \$4,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The four parking spaces closest to the old fire station have a 3% slope.

RECOMMENDATIONS

Resurface the parking spaces to reduce the slope to a maximum of 2% in all directions.











Facility:


3914

Boise Airport

Location: Economy Parking Lot for Concessions and Airlines

Schedule: 2021

Estimated Cost: \$5,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §403.3

The cross slope is 3%.

RECOMMENDATIONS

Resurface the route to reduce the cross slope to a maximum of 2%.







Facility:

4030

Boise Airport

Location: Economy Parking Lot Restroom Spaces

Schedule: 2021

Estimated Cost: \$200.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking space signs are 53" and 54" above the ground.

RECOMMENDATIONS

Remount the accessible parking signs at each accessible space at a minimum height of 60" above the ground.









Facility:

4314

Boise Airport

Location: Economy Parking Lot Shuttle Stop A

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §404.2.4.1

There is not adequate maneuvering clearance to operate the door due to the presence of a garbage can.

RECOMMENDATIONS

Relocate the garbage can.







Facility:

4111 Boise Airport

Location: Economy Parking Lot Shuttle Stop A

Schedule: 2021

Estimated Cost: \$400.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The four accessible parking space signs are 54.5" above the ground.

RECOMMENDATIONS

Remount the four accessible parking signs at a minimum height of 60" above the ground.











Facility:

4114

Boise Airport

Location: Economy Parking Lot Shuttle Stop A

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §208.2.4

Of the four spaces, there are no marked "Van accessible" spaces.

RECOMMENDATIONS

Expand one of the existing 108.5" wide spaces to be a 132" wide van accessible parking space. Add a "van accessible" parking sign at a minimum height of 60" above the ground.

Ensure that there is a 60" wide access aisle connecting to an accessible route.











Facility:


4112

Boise Airport

Location: Economy Parking Lot Shuttle Stop A

Schedule: 2021

Estimated Cost: \$2,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.2

Two of the accessible parking spaces are not of sufficient width at 90.5" wide.

RECOMMENDATIONS

Expand the accessible parking spaces to a minimum of 96" wide. Ensure at least one accessible parking space is marked as "van" accessible.













Facility:

4115

Boise Airport

Location: Economy Parking Lot Shuttle Stop A

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking spaces have a 2.9% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.











Facility:

4091

Boise Airport

Location: Economy Parking Lot Shuttle Stop D

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §305.2

The clear floor space has a 2.6% slope.

RECOMMENDATIONS

Resurface the 30"x48" clear floor space to have a maximum slope of 2% in all directions.





Facility:

4243

Boise Airport

Location: Economy Parking Lot Shuttle Stop D

Schedule: 2021

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.7.2, §405.7.3


The landing is not 60" long.

RECOMMENDATIONS

Expand the provided landing to ensure that the clear length is 60" long minimum to allow adequate turning space.









Facility:

4447

Boise Airport

Location: Economy Parking Lot Shuttle Stop D

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §405.2, §406.3


The curb ramp flares have a 11.3% slope.

The running slope of the curb ramp is 8.6%.

RECOMMENDATIONS


Resurface the curb ramp flares to ensure a maximum slope of 10%. Resurface the curb ramp to reduce the running slope to a maximum of 8.3%.













Facility:

3894

Boise Airport

Location: Economy Parking Lot Women's Restroom

Schedule: 2021

Estimated Cost: \$100.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §308.2.1

The soap dispenser is outside of the unobstructed forward reach range at 52" above the floor.

RECOMMENDATIONS

Lower the soap dispenser by 4" to meet the accessible reach range of 48" maximum above the floor.







Facility:

4122

Boise Airport

Location: Economy Parking Lot Women's Restroom

Schedule: 2022

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §604.5.2

The rear grab bar is located 6" from the side wall.

RECOMMENDATIONS

Replace the rear grab bar with one that is a minimum of 36" long minimum and extends from the centerline of the water closet 12" minimum on one side and 24" minimum on the other.











Facility:

4120

Boise Airport

Location: Economy Parking Lot Women's Restroom

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §604.7

The toilet paper dispenser is located out of the accessible reach range.

RECOMMENDATIONS

Remount the toilet paper dispenser to 7" minimum and 9" maximum in front of the water closet measured to the centerline of the dispenser.

The outlet of the dispenser shall be 15" minimum and 48" maximum above the floor and shall not be located behind the water closet.











Facility:

4263

Boise Airport

Location. Leonomy

Location: Economy Parking Lot, Middle of Parking lot, New Area

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 3.3-5.3% slope.

RECOMMENDATIONS

Resurface the parking space to reduce the slope to a maximum of 2% in all directions.









Facility:

4055

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$300.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking signs are 54.25" above the ground.

RECOMMENDATIONS

Remount the accessible parking signs at each accessible space at a minimum height of 60" above the ground.









Facility:

4210

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$500.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §302.3

The gap in the parking space is 1" wide and 0.75" deep.

RECOMMENDATIONS

Fill in the gap.











Facility:

4388

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3

The access aisles are not of sufficient width due to cement blocks.

RECOMMENDATIONS

Move the blocks to ensure that all accessible car parking spaces are a minimum of 96" wide and their adjacent access aisles are a minimum of 60" wide.









Facility:

4389

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §208.2.4

There are no marked "Van accessible" spaces.

RECOMMENDATIONS

Add a 132" wide van accessible parking space for every six vehicle parking spaces.

Add a "van accessible" parking sign at a minimum height of 60" above the ground. Ensure that there is a 60" wide access aisle connecting to an accessible route.









Facility:

4341

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 3% slope at the bottom.

RECOMMENDATIONS

Resurface the parking spaces to reduce the slope to a maximum of 2% in all directions.









Facility:

3838

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The access aisle has a 5% slope.

RECOMMENDATIONS

Resurface the access aisle to reduce the slope to a maximum of 2% in all directions.







Facility:

4056

Boise Airport

Location: Employee Accessible Parking

Schedule: 2021

Estimated Cost: \$3,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §208.2, §502.4

The Economy Employee parking lot has a total of 567 spaces, and four spaces are marked as accessible.

RECOMMENDATIONS

Install seven additional accessible parking spaces that are a minimum of 96" wide. Ensure at least two of the accessible parking spaces are marked as "van" accessible.

Install a 60" wide access aisle connecting to an accessible route. Install a sign 60" above the ground. Ensure that the maximum slope is 2% for accessible spaces and access aisle.











Facility:

4178

Boise Airport

Location: Long Term Lot Adjacent to Garage

Schedule: 2021

Estimated Cost: \$1,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.3

There are no access aisles.

RECOMMENDATIONS

Install access aisles connecting the accessible parking spaces to an accessible route. Two parking spaces shall be permitted to share a common access aisle. Each access aisle shall be 60" wide.











Facility:

4177 Boise Airport

Location: Long Term Lot Adjacent to Garage

Schedule: 2023

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502

The painted lines for the accessible parking spaces are faded.

RECOMMENDATIONS

Restripe and repaint the accessible parking spaces, access aisles, and ISA symbols.











Facility:

4146

Boise Airport

Location: New Parking Garage Crosswalk by Ramps

Schedule: 2022

Estimated Cost: \$2,000.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §705

The curb ramps do not have detectable warnings.

RECOMMENDATIONS

Install detectable warnings that contrast visually with the adjacent surface with either light-on-dark, or dark-on-light, are the width of the curb ramp, and have a depth of 24".











Facility:

4253

Boise Airport

Location: New Parking Garage Crosswalk by Stairs

Schedule: 2021

Estimated Cost: \$1,000.00




VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §405.2-§405.5, §406

No curb ramps are provided where the accessible route crosses a curb.

RECOMMENDATIONS

Install a curb ramp that is compliant with §406. The running slope shall not exceed 8.3% and the flare slope shall not exceed 10%.







Facility:

3240

Boise Airport

Location: Parking Garage

Schedule: 2021

Estimated Cost: \$10,000.00



VIOLATIONS


2010 ADA Sandards for Accessible Design Codes: §208.2


The parking garage has a total of 2,097 spaces and 43 accessible parking spaces.

RECOMMENDATIONS

Install 68 additional accessible parking spaces that are a minimum of 96" wide. Ensure at least 19 of the accessible parking spaces are marked as "van" accessible.

Install a 60" wide access aisle connecting to an accessible route. Install a sign 60" above the ground. Ensure that the maximum slope is 2% for accessible spaces and access aisle.









Facility:

3103

Boise Airport

Location: Parking Garage Benches

Schedule: 2022

Estimated Cost: \$1,000.00



VIOLATIONS


2010 ADA Standards for Accessible Design Codes: §903.4

The benches do not have sufficient back support.

RECOMMENDATIONS

Although the ADA regulations do not cover convenience benches, having benches with higher backs would provide a greater level of accessibility.

The back support must be 42" long minimum and extends from a point 2" maximum above the seat surface to a point 18" minimum above the seat surface.











Facility:

3952

Boise Airport

Location: Parking near 1A5

Schedule: 2021

Estimated Cost: \$100.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.6

The accessible parking sign is mounted 53" above the ground.

RECOMMENDATIONS

Remount the accessible parking sign at a minimum height of 60" above the ground.







Facility:

4505

Boise Airport

Location: Parking near 1A5

Schedule: 2021

Estimated Cost: \$2,500.00



VIOLATIONS

2010 ADA Standards for Accessible Design Codes: §502.4

The parking space has a 6.7% slope.

RECOMMENDATIONS

Reconstruct the parking space to reduce the slope to a maximum of 2% in all directions.



